HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER COLO 59-DILLY

HAER No. CO-82

Snake River Ditch
(Oro Grande Canal No. 1)
Headgate on the Snake River near the town of Keystone;
ending point at the Dillon Water Treatment Plant
Vicinity of Dillon
Summit County
Colorado

Documentation:

16 photos of setting, diversion, and ditch route (1994)

28 data pages (1994)


Mark Nash, Photographer, October 1994

- CO-82-1 VIEW OF DOWNSTREAM SIDE OF DIVERSION DAM ON THE SNAKE RIVER, LOOKING NORTHEAST. NOTE HEADGATE STRUCTURE ON NORTH BANK, SPILLWAY ON LEFT SIDE OF DAM, AND SPLASH LOGS ON DOWNSTREAM SIDE OF DAM.
- CO-82-2 UPSTREAM SIDE OF DIVERSION DAM ON THE SNAKE RIVER, LOOKING SOUTH-SOUTHWEST. NOTE BANK REINFORCEMENT ON LEFT AND SPILLWAY ON RIGHT.
- CO-82-3 NORTH SIDE OF DIVERSION DAM ON THE SNAKE RIVER SHOWING HEADGATE ON THE NORTH BANK. VIEW IS TO THE NORTHNORTHWEST.
- CO-82-4 HEADGATE AND FLUME AT THE BEGINNING OF THE SNAKE RIVER DITCH PASSING THROUGH BEAVER POND AREA, LOOKING EAST-SOUTHEAST.
- CO-82-5 LOG CRIBWORK INSTALLED TO REPAIR BREACH IN CANAL. VIEW IS TO THE NORTH-NORTHWEST.
- CO-82-6 REMAINS OF PLANK WALL NAILED TO POSTS WITHIN CANAL CONSTRUCTED TO PROTECT OUTSIDE CANAL BANK. VIEW IS TO THE WEST.
- CO-82-7 REMAINS OF PLANK WALL WITHIN CANAL CONSTRUCTED TO PROTECT OUTSIDE CANAL BANK, LOOKING SOUTHWEST. NOTE CROSS SUPPORT POLES EXTENDING TO HILLSIDE.


INDEX TO PHOTOGRAPHS

Snake River Ditch (Oro Grande Canal No. 1) HAER No. CO-82 (page 2)


- CO-82-8 FLUME BOX Y, LOOKING NORTH. CANAL HEADING RIGHT FOLLOWS HILLSIDE INTO DRAINAGE; FLUME HEADING LEFT CROSSED GULCH ON A TRESTLE. NOTE CONCRETE ABUTMENTS NEAR TOP RIGHT INSTALLED IN 1935 TO PREVENT WATER FROM ESCAPING CANAL AT OLD TRESTLE ENTRANCE.
- CO-82-9 FLUME BOX Y, LOOKING SOUTH. CANAL IN FOREGROUND FOLLOWS HILLSIDE INTO DRAINAGE; FLUME HEADING TO RIGHT CROSSED GULCH ON A TRESTLE.
- CO-82-10 CANAL CUT THROUGH SHALE BEDROCK ON PROMINENT POINT, LOOKING NORTH-NORTHEAST. NOTE CONCRETE ABUTMENTS PROBABLY INSTALLED IN 1935 TO PREVENT WATER FROM ESCAPING THROUGH A CANAL BANK BREACH.
- CO-82-11 REMNANTS OF FLUME BOX WITHIN CANAL. NOTE THE UPRIGHT SIDE POSTS BOLTED TO BASE STRINGER AND HORIZONTAL BOARD SIDE WALLS. VIEW IS TO THE SOUTHEAST.
- CO-82-12 LOG FOUNDATION ELEMENTS OF THE SAWMILL ADJACENT TO THE CANAL, LOOKING EAST. BARREN AREA IN FOREGROUND IS DECOMPOSING SAWDUST. DIRT PILE IN BACKGROUND IS THE EDGE OF THE SUMMIT COUNTY LANDFILL.
- CO-82-13 REMNANTS OF FLUME BOX LEADING TO SLUMPED TUNNEL ENTRANCE. VIEW IS TO THE NORTHWEST.
- CO-82-14 ANGULAR QUARTZITE ROCK REINFORCEMENT ON INTERIOR OF OUTSIDE CANAL BANK, LOOKING SOUTH-SOUTHEAST. CANAL ROUTE VISIBLE ALONG HILLSIDE NEAR TOP LEFT. NOTE DILLON RESERVOIR, HIGHWAY 6, AND NEW RESIDENTIAL CONSTRUCTION AT RIGHT AND CENTER.
- CO-82-15 ROUTE OF CANAL NORTHWEST OF THE DILLON CEMETERY. CANAL PASSES BELOW HILLSIDE IN FOREGROUND, THROUGH THE LOWER EDGE OF THE TREES ON LEFT, ON FAR SIDE OF SMALL VALLEY JUST RIGHT OF CENTER, AND AROUND THE PROMINENT POINT ON THE RIGHT. VIEW IS TO THE EAST-SOUTHEAST.
- CO-82-16 ROUTE OF CANAL EAST OF THE DILLON CEMETERY, LOOKING SOUTHEAST.




Location of photographic points.



Location of photographic points.



Location of photographic points.



Location of photographic points.